



MODEL

G01 (X3)	G02 (X4)	G12 (7 Series)	G30 (5 Series Sedan)
G32 (6 Series Gran Turismo)			

SITUATION

Check Control Messages displayed:

- 02D6 Electromechanical holding brake
- 02D7 Electromechanical holding brake failed

Fault messages stored in Dynamic Stability Control (DSC) unit:

- 0x480766 (PB_MOTOR_SHORT_TO_B_PLUS or PB_MOTOR_SHORT_TO_GND)
- 0x480767 (PB_MOTOR_SHORT_TO_B_PLUS_RR or PB_MOTOR_SHORT_TO_GND_RR)

CAUSE

The DSC unit

CORRECTION

Replace DSC unit

PROCEDURE

For conditions that are similar to the situation described:

1. Perform diagnosis with the latest version of ISTA, working through test module.
2. If no other solution is diagnosed by ISTA, replace the DSC, following repair instructions **34 52 519**
Replace DSC control unit.

PARTS INFORMATION

All required parts are original replacement parts and can be found in the Electronic Parts Catalog.

WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks or the BMW Certified Pre-Owned Program.

Defect Code:	3452101400	
Labor Operation:	Labor Allowance:	Description:

00 00 006	Refer to KSD2	Performing “vehicle test” (with vehicle diagnosis system – checking faults) (Main work)
Or:		
00 00 556	Refer to KSD2	Performing “vehicle test” (with vehicle diagnosis system – checking faults) (Plus work)
And:		
61 21 528	Refer to KSD2	Connect an approved battery charger/power supply (indicated in KSD2 as “Charging battery”)
And, as necessary:		
61 00 006	Work time (WT)	Performing vehicle diagnosis – test module
And:		
34 52 519	Refer to KSD2	Replacing DSC control unit (after vehicle diagnosis)
And:		
61 00 730	Refer to KSD2	Programming/encoding control unit(s)

And, additionally for the:

e-Vehicles

Labor Operation:	Labor Allowance:	Description:
61 25 910	Refer to KSD2	Recharging high-voltage battery unit (to high voltage charging socket)

If you are using a Main labor code for another repair, use the Plus code labor operation 00 00 556 instead of 00 00 006.

Refer to KSD2/AIR for the corresponding flat rate unit (FRU) allowances.

Work time labor operation code 61 00 006 is not considered a Main labor operation; however, it does require an individual punch time and an explanation on the repair order and in the claim comments section.

During the same workshop visit, if a vehicle also requires another Technical Campaign or repair that also includes programming and encoding the control units, the programming procedure may only be invoiced one time.

And, as needed:

Sublet – Bulk Materials

Sublet Code 4	See the sublet reimbursement calculations below	Reimbursement for the repair-related bulk materials (Do not use part numbers for claim submission)
----------------------	---	--

Sublet reimbursement calculation for claiming the applicable repair-related bulk materials (BMW part numbers) is at the dealer net price for the “quantities used” plus your center’s handling.

BMW Antifreeze/Coolant: When applicable, claim for the amount that is needed to replace what was drained with a “50/50 coolant/water solution.”

Enter this material cost in sublet and itemize the amount on the repair order and in claim comment section.

Vehicle Programming and Encoding

A. The programming procedure automatically reprograms and encodes all vehicle control modules which do not have the latest software i-level. If one or more control module failures occur “during” this programming procedure:

- Please claim this “consequential” control module-related repair work under the defect code listed in this bulletin with the applicable KSD2/AIR labor operations.

Please explain this additional work (The why and what) on the repair order in the claim comments section.

B. For control module failures that occurred “prior” to performing this programming procedure; and/or

C. Other work/repairs that results from performing ISTA diagnostics and the related test plans:

- When “covered” under an applicable limited warranty, claim this control module-related repair work using the applicable defect code and labor operations (including diagnosis) in KSD2/AIR.