

SITUATION

The driver's side or passenger's side door may not open to the highest position.

CAUSE

Insufficient lifting force from gas pressurized damper spring.

CORRECTION

Replace gas pressurized damper spring with the next highest opening force level.

PROCEDURE

CRUBB6116-56	1. Open affected door and find parts information label located on gas pressurized spring as shown.	
	2. Locate the part number as shown.	
CRUSB5116-57	3. Replace damper as follows:	
	Current part #	Replacement part#
	7312686	7375528*
	7375528	7404764* (+30N Force)
	7404764	New 7404764 (+60 N Force)
	Do not install the highest force immediately; the amount of force required may be uncomfortable for the customer. Only fit a damper with the next highest damping force and recheck. Only replace the affected side.	
	Because a stronger damper is fitted, the customer must be	

informed of possible effects on necessary closing force.

PARTS INFORMATION

Copyright ©2022 BMW of North America, Inc.

Part Number	Description	Quantity
51 22 7 375 528	Gas Pressurized Spring (plus 30N force)	
Or:		
51 21 7 404 764 Gas Pressurized Spring (plus 60N force)		1 or 2

WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks.

Defect Code: 51 21 23 59 00	
-----------------------------	--

Repairing One Side:

Labor Operation:	Labor Allowance:	Description:
51 21 280	Refer to KSD2	Removing and installing or replacing door stop of left or right front door (Gas-filled shock absorber) (Main work).
Or:		
51 21 780	Refer to KSD2	Removing and installing or replacing door stop of left or right front door (Gas-filled shock absorber) (Plus work).

Or:

Repairing Both Sides:

Labor Operation:	Labor Allowance:	Description:
51 21 281	Refer to KSD2	Removing and installing or replacing door stop of both front doors (Gas-filled shock absorbers) (Main work).
Or:		
51 21 781	Refer to KSD2	Removing and installing or replacing door stop of both front doors (Gas-filled shock absorbers) (Plus work).