



## SUNROOF DOES NOT MOVE

This Service Information Bulletin (Revision 1) replaces SI B54 05 21 **dated October 2021**.

**What's New** (Specific text highlighted):

- Correction
- Procedure

## MODEL

E-Series	Model Description
F90	M5 Sedan
G12	7 Series Sedan
G30	5 Series Sedan

## SITUATION

The sunroof will not operate in either direction.

There are **NO** faults stored related to the sunroof. **If the vehicle has any faults stored related to the sunroof, this bulletin does not apply.**

## CAUSE

A software error in the FZD (Roof function center).

## CORRECTION

Program the vehicle using **ISTA 4.32.1x** or higher (estimated released **November 2021**).

## PROCEDURE

1. Perform a vehicle test to ensure no faults are present. If faults related to the sunroof are present, this bulletin does not apply: Continue troubleshooting with ISTA.
2. If no faults are present but the sunroof will not operate in either direction, perform a control module reset of the FZD using control module functions with ISTA.

After the FZD module reset, does the sunroof operate?

Yes: Continue to step 3.

No: Continue troubleshooting with ISTA, this bulletin does not apply.

3. Is the current I-level of the vehicle at or above the following affected I-Levels? (depending on model)

**S15A vehicles:** S15A-20-11-5xx

**S18A vehicles:** S18A-21-03-5xx

Yes: Continue to step 4.

No: Continue troubleshooting in ISTA, this bulletin does not apply.

4. Program the vehicle using **ISTA 4.32.1x** or higher (estimated released **November 2021**). Target I-Level of at least S15A/S18A-21-11-520.

## PARTS INFORMATION

Parts are not required.

## CLAIM INFORMATION

During this workshop visit, the affected vehicle may show one or more programming and encoding Technical Campaign repairs open, the programming and encoding procedure may only be invoiced one time.

**Select one of these open Technical Campaigns to perform and submit for updating the vehicle's software to the required I-level or higher.**

Please be sure to perform any additional before and/or after work (including attaching labels) as required by the open campaigns on the vehicle. Close any remaining open programming and encoding Campaign repairs as outlined in the corresponding Service Information Bulletin.

Only if the above situation does not apply, the BMW software solution is then:

Covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks, or the BMW Certified Pre-Owned Program as described below.

<b>Defect Code:</b>	<b>6131740200</b>	<b>Roof functions centre FZD Software error / internal device fault</b>
---------------------	-------------------	---

Refer to AIR for the corresponding flat rate unit (FRU) allowances.

<b>Labor Operation</b>	<b>Description</b>	<b>Labor Allowance</b>
00 00 006	Performing vehicle test (with vehicle diagnosis system – checking faults) (Main work)	Refer to AIR
Or:		
00 00 556	Performing vehicle test (with vehicle diagnosis system – checking faults) (Plus work)	Refer to AIR
And:		
61 21 528	Support voltage of the vehicle electrical system / recharge vehicle electrical system battery	Refer to AIR
And		
61 00 730	Programming/encoding control unit(s)	Refer to AIR

If you are using a Main labor code for another repair, use the Plus code labor operation 00 00 556 instead of 00 00 006, or exclude (including 61 21 528) when the Vehicle Test is included in another repair.

### **Programming and Encoding - Vehicle Control Units (RO and Claim Comments Required)**

This procedure automatically reprograms and encodes any vehicle control modules that do not have the latest software I-level.

If one or more control modules fail during the reprogramming procedure, claim the required consequential repair work procedures to address this issue (including performing the IRAP Control Unit Recovery first as required, refer to the SIB in AIR) under the Defect Code in this bulletin with the labor operations in AIR that apply.

Please explain the additional work procedures that were performed (The why and the what) on the repair order and in the claim comments.

For covered repairs that address control module failures that occurred prior to performing this reprogramming procedure, claim this work with the Defect Code and labor operations (including diagnosis) in AIR that apply.

Based on which one applies to your center, please refer to [SI B01 01 20](#) or [B01 07 20](#) for the applicable procedure for documenting, claiming, and explaining, on the RO and in the claim comments, your diagnosis work time (WT), job/repair work time (WT), and the vehicle repairs your center performed, unless otherwise required by State law.

### **Other Repairs**

If other eligible and covered work is performed because of performing the ISTA diagnostics and related test plans, claim this work with the applicable Defect Code and the labor operations listed in AIR (including diagnosis).

### **QUESTIONS REGARDING THIS BULLETIN**

Technical inquiries	Submit feedback at the top of this bulletin
Warranty inquiries	Please contact the Warranty department by either using the Live Chat that's available in the Warranty Documentation Portal or through IDS by selecting Coverage, Policy, Coding Questions and Mileage Corrections
Parts inquiries	Submit an IDS ticket to the Parts Department