



MODEL

I01 (i3)	I15 (i8 Roadster)
I12 (i8)	

SITUATION

BMW Group is conducting a Voluntary Safety Recall (effective September 26, 2018) on certain BMW TurboCord chargers which can be used with Model Year 2014-2019 BMWi BEV and Rex vehicles produced from 03/07/2014 up to 08/21 2018.

Approximately 2,232 vehicles are affected by this recall.

Affected vehicles show the campaign as “Open” when checked either in Warranty Vehicle Inquiry, AIR or ISPA Next and identified with the description:

0061850400: B611318 Recall: Check TurboCord Portable EV Charger.

All of the other systems including DAR and the RDR system will show the Stop Sale Sign starting tomorrow. Please utilize the Inventory Campaign Details under ROSS which shows all vehicles that have a Stop Sale in your inventory.

CAUSE

Affected cables were not produced to specifications due to one or more incompatible capacitors on the printed circuit board assembly. An affected cable could overheat and lead to a thermal event or present a shock hazard to the user.

CORRECTION

When the Affected Vehicle “is equipped” with this accessory:

- Inspect the serial number printed on the TurboCord Charger label, either on the charger body 110/240V wall plug, or on the shipping box.
- Enter the serial number into the “Serial Number Check” attachment, and find out if it is affected by this Recall.
- Replace the TurboCord Charger with the improved part, if the serial number is a “bad part” according to the “Serial Number Check” attachment.

The recalled TurboCord Charger is to be returned to the Warranty Parts Return Center (WPRC) via the normal parts return process upon your center’s receipt of the DCSnet part return request.

PROCEDURE

BMW TurboCord EV Portable Charger 110/240V



GRUSB6118-13



GRUSB6118-14

Serial number location on the product label placed on the TurboCord Charger shipping box



GRUSB6118-15

Serial number location on the charger body of the TurboCord Charger

PARTS INFORMATION

Not all the Affected Vehicles that show this recall open are equipped with this accessory.

Only order this part in the quantities needed to address customers' vehicles that are confirmed to be equipped with this accessory.

Part Number	Description	Quantity
61 44 2 448 670	BMW TurboCord Charger	1

WARRANTY INFORMATION

For Affected Vehicles determined to be "equipped" and "not equipped" with this accessory, reimbursement for this Recall Action will be via normal claim entry utilizing the following information:

--	--	--

Defect Code:	0061850400
---------------------	-------------------

Completion "before" vehicle delivery to the customer or the vehicle is already in the workshop

Labor operation:	Labor allowance:	Description:
00 66 976	3 FRU	Check and if necessary, replace charging cable accessories (Plus work)

Or:

Completion after vehicle delivery to the customer (with no other Main work will be performed/claimed)

Labor operation:	Labor allowance:	Description:
00 66 280	5 FRU	Check and if necessary, replace charging cable accessories (Main Work)

Note: If the vehicle is "not equipped" with this accessory (no part claimed), please explain that on the repair order and the claim comments.

Posted: Tuesday, October 30, 2018

[180925_Dealer Process_Rev01.pdf](#)

[B611318 Recall Notice.pdf](#)

[2018-eVehicles-BMW-MINI-TurboCordPortableCharger-QA-\(24Sep2018\).pdf](#)

[2018-eVehicles-TurboCordPortableCharger-CustomerAgreement.pdf](#)

[Faulty Serial Numbers Check_BMW_MINI.pdf](#)