



This Service Information Bulletin (Revision 2) replaces SI B62 05 19 **dated May 2019**.

What's New (Specific text highlighted):

- Integration level updated

MODEL

G01 X3	G02 X4
--------	--------

Vehicles produced up to 7/1/2019 production

SITUATION

Customer noticed that their compass display was deleted from the Instrument Cluster (KOMBI) after recent programming. It still appears in the CID widget display.

CAUSE

Software error in the KOMBI

CORRECTION

Program/encode the vehicle to Integration level (I-level) S15A-19-11-534 or higher.

PROCEDURE

1. Perform diagnosis with the latest version of ISTA, working through test module, if needed.
2. Is the current integration level S15A-19-11-534 or higher?

NO: Proceed to Step 3

YES: Do not program the vehicle and perform diagnosis with ISTA.

3. Program the vehicle using ISTA 4.21.1x or higher (released December 2019).

Model	Target integration level
G01 G02	S15A-19-11-534 or higher

Note that ISTA will automatically reprogram and code all programmable control modules that do not have the latest software.

Always connect a BMW-approved battery charger/power supply ([SI B04 23 10](#)) when performing programming.

For information on programming and coding with ISTA, refer to CenterNet / TIS / Technical Documentation / Programming and Diagnostics / Programming Documentation.

PARTS INFORMATION

Parts replacement will not provide a solution.

WARRANTY INFORMATION

When the BMW software solution becomes available, the following repair is covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks or the BMW Certified Pre-Owned Program.

Defect Code:	6211201800	KOMBI display/pixel/backlighting (in the instrument cluster) Incorrect/incomplete display
Labor Operation:	Labor Allowance:	Description:
00 00 006	Refer to AIR	Performing vehicle test (with vehicle diagnosis system – checking faults) (Main work)
Or:		
00 00 556	Refer to AIR	Performing vehicle test (with vehicle diagnosis system – checking faults) (Plus work)
And:		

61 21 528	Refer to AIR	Connect an approved battery charger/power supply (indicated in AIR as Charging battery)
And:		
61 00 730	Refer to AIR	Programming/encoding control unit(s)

If you are using a Main labor code for another repair, use the Plus code labor operation 00 00 556 instead of 00 00 006.

Refer to AIR for the corresponding flat rate unit (FRU) allowances.

During the same workshop visit, if a vehicle also requires another Technical Campaign or repair that also includes programming and encoding the control units, the programming procedure may only be invoiced one time.

Programming and Encoding - Vehicle Control Units

The programming procedure automatically reprograms and encodes all vehicle control modules which do not have the latest software i-level. If one or more control module failures occur during this programming procedure:

Please claim this consequential control module-related repair work under the defect code listed in this bulletin with the applicable AIR labor operations.

Please explain this additional work (The why and what) on the repair order and in the claim comments section.

For control module failures that occurred prior to performing this programming procedure:

When covered under an applicable limited warranty, claim this control module-related repair work using the applicable defect code and labor operations

Other Repairs

If other eligible and covered work is performed as a result of performing the ISTA diagnostics and related test plans, claim this work with the applicable defect code and the labor operations (including diagnosis with separate punch times) that are listed in AIR.