



This Service Information bulletin supersedes SI B65 04 14 **dated February 2015.**

What is new

- Model: Added G12 and G30
- Situation: Fault code description added
- Correction: Added to reinforce the need to make the repair.
- Procedure: Added clarification of alternate procedures and test plan feedback statement correction
- Added safety and malfunction information after Procedure.

MODEL

F01 (7 Series Sedan)	F02 (7 Series Sedan LWB)	F06 (6 Series Gran Coupe)	F07 (5 Series Gran Turismo)
F10 (5 Series Sedan)	F12 (6 Series Convertible)	F13 (6 Series Coupe)	F25 (X3)
F30 (3 Series Sedan)	F15 (X5)	F16 (X6)	F26 (X4)
F32 (4 Series Coupe)	F34 (3 Series Gran Turismo)	F82 (M4 Coupe)	UPDATE! G12 F02 (7 Series Sedan LWB)
UPDATE! G30 (5 Series Sedan)			

SITUATION

According to the customer, the airbag warning light was on, but it may not be on when the vehicle arrives in the workshop.

1. ACSM fault code “930A60 – Seat occupancy detection, front passenger; malfunction” is stored. The fault may or may not currently be present.

Or

2. **UPDATE!** ACSM fault code “930A1C – Front passenger seat occupancy detection transmitting fault (moisture)” is stored. The fault may or may not currently be present.

CAUSE

The front passenger seat occupancy mat consists of a seat occupancy mat with a capacitive sensor system. This means a front passenger is detected by measuring the resistance of the human body. The fault is set when moisture is detected on the mat itself.

CORRECTION

UPDATE! It is important to find out the root cause of the fault in order to fix the vehicle right the first time and preventing the customer from returning with the same complaint. This service information guides you through the troubleshooting process based on the 2 scenarios provided in the Procedure.

PROCEDURE

Prior to diagnosing faults 930A60 or 930A1C with ISTA, diagnose any other airbag-related faults (including power management) first.

UPDATE! There are two different approaches to repairing this situation based on the status of the warning indicator lamp and stored fault. Select the appropriate method as follows:

The fault is currently not present and the airbag warning light is not currently illuminated:

1. Complete the test plan “Seat occupancy detection, front passenger” linked to the fault code.
2. **UPDATE!** The test plan feedback states the following:
 - There was a temporary malfunction in the front passenger’s seat occupancy detection system
 - This is probably attributed to high moisture levels.
 - This fault is currently not active and can be deleted.
 - **Do Not** replace the seat occupancy detection.

UPDATE! Although this information is accurate, it is not necessarily complete. There can be many reasons for a malfunction, therefore continue with the following steps.

3. Select “Check seat occupancy detection system” to ensure the system is working properly. A person must sit in the passenger’s seat while the technician is viewing ISTA to see if the status changes from “Person not detected” to “Person detected.” Try this several times.
4. If the status changes, the system is functioning properly. **Do not replace any parts** and clear the faults. If the status does not change, follow the test plan recommendations.
5. Check for any external signs of moisture or spilled liquid (coffee, soda or water on the seat leather).
6. Check that there are no complaints of water leaks in the vehicles from windows or the sunroof. Address these complaints as needed.

The fault is currently present and the airbag warning light is currently illuminated:

1. Complete the test plan “Seat occupancy detection, front passenger” that is linked to the fault code.
2. The test plan states: “The front passenger seat occupancy detector shows a malfunction because of excess moisture. Dry the front passenger seat. For this purpose, switch on the seat heating. Note: Drying the seat can take up to 2 days.”
3. If the seat does not have seat heating, the leather on top of the seat must be partially removed and the CIS mat ventilated with a heating fan. Also check the position and mounting of the seat for any folds or moisture stains. Once the seat mat is sufficiently dried, proceed to the next step.
4. Select “Check seat occupancy detection system” to ensure the system is working properly. A person must sit in the passenger’s seat while the technician is viewing ISTA to see if the status changes from “Person not detected” to “Person detected.” Try this several times.
5. If the status changes, the system is functioning properly. **Do not replace any parts** and clear the faults. If the status does not change, follow the test plan recommendations.
6. **Seat mats that have moisture damage caused by outside influences (coffee, soda, water, spillage, etc.) are not covered under the limited warranty. This is not a defect in materials or workmanship.**



UPDATE!

Note: Refer to the owner’s manual about safety for passenger sitting in the front seat and

external influences causing malfunction and deactivation of the air bag system.

UPDATE!

Malfunction of the automatic deactivation system:

When transporting older children and adults, the front-seat passenger airbags may be deactivated in certain sitting positions. In this case, the indicator lamp for the front-seat passenger airbags lights up.

In this case, change the sitting position so that the front-seat passenger airbags are activated and the indicator lamp goes out.

- If it is not possible to activate the airbags, have the person sit in the rear.
- Do not attach covers, cushions, ball mats or other items to the front passenger seat unless they are specifically determined to be safe for use on the front passenger seat.
- Do not place any electronic devices on the passenger seat if a child restraint system is to be installed on it.
- Do not place objects under the seat that could press against the seat from below.
- No moisture in or on the seat.

WARRANTY INFORMATION

As noted above, a failure resulting from damage that is caused by outside influences is not a warranty matter.

However, if the ISTA diagnostics with related test plans, or other troubleshooting procedures result in eligible and covered work, claim this work with the applicable defect code and labor operations listed in KSD2.

Tuesday, September 5, 2017