



## RECALL 22V-483: VALET PARKING MODE

This Service Information Bulletin (Revision 1) replaces SI B65 08 22 **dated July 2022**.

**What's New** (Specific text highlighted):

- Cause
- Correction
- Procedure
- Claim Information

## MODEL

E-Series	Model Description	Production Date
G26 BEV	i4 Gran Coupe	October 14, 2021 – July 1, 2022

## AFFECTED VEHICLES

Vehicles which require this Recall Campaign to be completed will show it as "Open" when checked either in AIR, the "Service Menu" of DCSnet (Dealer Communication System), ISPA Next or Warranty Vehicle Inquiry.

## SITUATION

BMW AG is conducting a Voluntary Non-Compliance Recall (effective July 5, 2022) on certain Model Year 2022 BMW i4 Gran Coupe vehicles that were produced between November 11, 2021 and June 28, 2022.

When in Valet Parking Mode, warning messages may not be displayed in the CID (Central Information Display). As a result, there is potential non-compliance with a Federal requirement.

The Recall Notice and Q&A have been attached for further information.

## CAUSE

Software error in the MGU (Media Graphics Unit).

## CORRECTION

Program the vehicle to S18A-22-07-520 or higher.

## PROCEDURE

1. Determine the vehicle's current I-level by either using AIR or the ISPA NEXT application. If needed, use the latest ISTA to work through test modules.

2. Is the current vehicle integration level:

Model	Integration level
G26 BEV	<b>Lower than S18A-22-07-520</b>

**YES:** Proceed to Step 3

**NO:** No further action necessary

3. Program the vehicle using ISTA 4.36.2x or higher (released July 18, 2022).

Model	Target integration level
G26 BEV	<b>S18A-22-07-520 or higher</b>

Note that ISTA will automatically reprogram and code all programmable control modules that do not have the latest software.

4. Did the vehicle program correctly the first time?

**YES:** No further action necessary

**NO:** Program the vehicle a 2<sup>nd</sup> time and claim WP #2 or #5.

**Always connect a BMW-approved battery charger/power supply ([SI B04 23 10](#)).**

### CLAIM INFORMATION

During this workshop visit, the affected vehicle may also show one or more programming and encoding Technical Campaign repairs open, the programming and encoding procedure may only be invoiced one time.

**When the above applies and the vehicle must be programmed a second time per the measures plan, then submit for Work Package # 2 or # 5 below as applicable for updating the vehicle to the required I-level or higher**

**Please be sure to also perform any additional before and/or after work (including attaching labels) as required by the open campaigns on the vehicle. Close any other open programming and encoding Campaign repairs as outlined in the corresponding Service Information Bulletin.**

As determined by the above, reimbursement for this Recall will be via normal claim entry utilizing the work package information below that applies.

Defect Code:	0065820300	U06 G26 BEV G28 BEV Program control units (head unit)
--------------	------------	-------------------------------------------------------

**Completion before the first vehicle delivery to a customer or the vehicle is already in the workshop**

Work Pkg	Labor Operation	Description (Plus work)	Labor Allowance
# 1	00 72 828	MGU control unit - programming and encoding <b>(One-time)</b> the vehicle control units, includes Carrying out vehicle test <b>(00 00 556/61 21 528)</b>	8 FRU
Or, when required:			
# 2	00 72 836	MGU control unit - programming and encoding <b>(Two times per the measures plan)</b> the vehicle control units, includes Carrying out vehicle test <b>(00 00 556/61 21 528)</b>	12 FRU
Or:			
# 3	00 72 829	Programming and encoding the vehicle control units was performed in conjunction with <b>another campaign/repair prior to or during this workshop visit</b> (vehicle is already at the specified Target integration level or higher, no repair is necessary)	1 FRU

Or:

**The vehicle arrives at your center and this Recall shows open (No other Main work will be performed or claimed during this workshop visit)**

Work Pkg	Labor Operation	Description (Main work)	Labor Allowance
# 4	00 72 249	MGU control unit - programming and encoding <b>(One-time)</b> the vehicle control units, includes Carrying out vehicle test <b>(00 00 006/61 21 528)</b>	10 FRU
Or, when required:			
# 5	00 72 257	MGU control unit - programming and encoding <b>(Two times per the measures plan)</b> the vehicle control units, includes Carrying out vehicle test <b>(00 00 006/61 21 528)</b>	14 FRU
Or:			

# 6	00 72 250	Programming and encoding the vehicle control units was performed in conjunction with <b>another campaign/repair prior to this workshop visit</b> (vehicle is already at the specified Target integration level or higher, no repair is necessary)	1 FRU
-----	-----------	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------

Only one of the flat rate labor operation codes listed above can be used for claim submission/reimbursement purposes. Also, only one Main work flat rate labor operation code can be claimed per workshop visit.

### Claim Repair Comments

Only reference the SIB number and the work package (Pkg) number performed in the RO technician notes and the claim comments (For example: B65 08 22 WP 1), unless otherwise required by State law.

### Programming and Encoding - Vehicle Control Units (RO and Claim Comments Required)

This procedure automatically reprograms and encodes any vehicle control modules that do not have the latest software I-level.

If one or more control modules fail during the reprogramming procedure, claim the required consequential repair work procedures to address this issue (including performing the IRAP Control Unit Recovery first as required, refer to the SIB in AIR) under the Defect Code in this bulletin with the labor operations in AIR that apply.

Please explain the additional work procedures that were performed (The why and the what) on the repair order and in the claim comments.

For covered repairs that address control module failures that occurred prior to performing this reprogramming procedure, claim this work with the Defect Code and labor operations (including the diagnosis that applies\*) in AIR that apply.

\*Based on which one applies to your center, please refer to [SI B01 01 20](#) or [B01 07 20](#) for the applicable procedure for documenting, claiming, and explaining, on the RO and in the claim comments, your diagnosis work time (WT), job/repair work time (WT), and the vehicle repairs your center performed, unless otherwise required by State law.

### Alternative Mobility Solution (AMS) for Vehicle Owners (RO and Claim Comments Required)

This Recall repair qualifies for Alternative Mobility Solution (AMS) expense reimbursement, claim this item under the Defect Code noted above as follows:

Sublet Code 2 - Itemize the AMS sublet amount on the repair order and in the claim comment section.

Please refer to [SI B01 29 16](#) for additional information.

### Reimbursement of Prior Customer-Pay Repairs (TREAD Act)

Based on the issue and the age of the Affected Vehicles being addressed by this Safety Recall Campaign, a reimbursement request for a qualifying prior customer-pay repair is not likely.

However, if you do receive a reimbursement request from a customer for a prior repair that may qualify, please contact the Warranty department (include a legible copy of the invoice) through IDS by selecting Coverage, Policy, Coding Questions and Mileage Corrections. The Warranty department will review and respond to your inquiry accordingly.

### FEEDBACK REGARDING THIS BULLETIN

Technical Feedback	To submit feedback for the technical topics of this bulletin: Submit your feedback in the rating box at the top of this bulletin
Warranty Feedback	To submit feedback for the CLAIMS section of this bulletin: Submit an IDS ticket to the Warranty Department, or use the chat available in the Warranty Documentation Portal
Parts Feedback	To submit feedback for the PARTS section of this bulletin: Submit an IDS ticket to the Parts Department

Supporting Materials

[picture as pdf B650822\\_22V-483-FAQ-\(15Jul2022\).pdf](#)

[picture as pdf B650822 Recall Notice.pdf](#)