



SERVICE ACTION: PROGRAM VEHICLE (I20)

Please perform the procedure outlined in this Service Information on all affected vehicles before customer delivery. In the event the customer has already taken delivery of the vehicle, please perform the procedure the next time the vehicle is in the shop.

MODEL

E-Series	Model Description	Production Date
I20	iX Sports Activity Vehicle	November 1*, 2021 to March 25, 2022

* start of series production

AFFECTED VEHICLES

Vehicles which require this Campaign to be completed will show it as "Open" when checked either in AIR, the "Service Menu" of DCSnet (Dealer Communication System), ISPA Next or Warranty Vehicle Inquiry.

SITUATION

The software update improves functions of numerous control units, most importantly the telematics control unit, drivers assistance camera and head unit.

The software update improves the following:

- Check Control message "Emergency call system failure". However, the emergency call function itself is not affected.
- The High-beam Assistant reacts too sensitively to oncoming light sources
- Individual language packages in the vehicle are erroneously deleted
- Prevents unwarranted Check Control messages

Overall these faults can lead to uncertainty for the customer, but are not relevant to safety or model certification.

CAUSE

Software in the vehicle.

CORRECTION

Program the vehicle.

PROCEDURE

1. Determine the vehicle's current I-level by either using AIR or the ISPA NEXT application. If needed, use the latest ISTA to work through test modules.
2. Is the current vehicle integration level:

	Integration level
Model	
I20	Lower than I020-22-03-535

YES: Proceed to Step 3

NO: Further diagnosis with ISTA is needed

3. Program the vehicle using ISTA 4.34.25 or higher (released mid-March 2022).

	Target integration level
Model	
I20	I020-22-03-535 or higher

Note that ISTA will automatically reprogram and code all programmable control modules that do not have the latest software.

Always connect a BMW-approved battery charger/power supply ([SI B04 23 10](#)).

PARTS INFORMATION

Parts exchange will not provide a solution.

CLAIM INFORMATION

During this workshop visit, the affected vehicle may also show one or more programming and encoding Technical Campaign repairs open, the programming and encoding procedure may only be invoiced one time.

Select one of these open Technical Campaigns to perform and submit for updating the vehicle to the required I-level or higher.

Please be sure to also perform any additional before and/or after work (including attaching labels) as required by the open campaigns on the vehicle. Close any other open programming and encoding Campaign repairs as outlined in the corresponding Service Information Bulletin.

As determined by the above, reimbursement for this Service Action will be via normal claim entry utilizing the work package information below that applies.

Defect Code:	0084980100	---
---------------------	-------------------	-----

Completion before the first vehicle delivery to a customer or the vehicle is already in the workshop

Work Pkg	Labor Operation	Description (Plus work)	Labor Allowance
# 1	00 72 624	Programming and encoding the vehicle control units (includes providing support voltage for the vehicle electrical system and performing a vehicle test)	9 FRU
Or:			
# 2	00 72 625	Programming and encoding the vehicle control units was performed in conjunction with another campaign/repair prior to or during this workshop visit (vehicle is already at the specified Target integration level or higher, no repair is necessary)	1 FRU

Or:

The vehicle arrives at your center and this Service Action shows open (No other Main work will be performed or claimed during this workshop visit)

Work Pkg	Labor Operation	Description (Main work)	Labor Allowance
# 3	00 72 097	Programming and encoding the vehicle control units (includes providing support voltage for the vehicle electrical system and performing a vehicle test)	11 FRU
Or:			
# 4	00 72 098	Programming and encoding the vehicle control units was performed in conjunction with another campaign/repair prior to this workshop visit (vehicle is already at the specified Target integration level or higher, no repair is necessary)	1 FRU

Only one of the flat rate labor operation codes listed above can be used for claim submission/reimbursement purposes. Also, only one Main work flat rate labor operation code can be claimed per workshop visit.

Claim Repair Comments

Only reference the SIB number and the work package (Pkg) number performed in the RO technician notes and the claim comments (For example: B84 05 22 WP 1), unless otherwise required by State law.

Programming and Encoding - Vehicle Control Units (RO and Claim Comments Required)

This procedure automatically reprograms and encodes any vehicle control modules that do not have the latest software I-level.

If one or more control modules fail during the reprogramming procedure, claim the required consequential repair work procedures to address this issue (including performing the IRAP Control Unit Recovery first as required, refer to the SIB in AIR) under the Defect Code in this bulletin with the labor operations in AIR that apply.

Please explain the additional work procedures that were performed (The why and the what) on the repair order and in the claim comments.

For covered repairs that address control module failures that occurred prior to performing this reprogramming procedure, claim this work.

Based on which one applies to your center, please refer to **[SI B01 01 20](#)** or **[B01 07 20](#)** for the applicable procedure for documenting, claiming, and explaining, on the RO and in the claim comments, your diagnosis work time (WT), job/repair work time (WT), and the vehicle repairs your center performed, unless otherwise required by State law.

QUESTIONS REGARDING THIS BULLETIN

Technical inquiries	Submit feedback at the top of this bulletin
Warranty inquiries	Please contact the Warranty department by either using the Live Chat that's available in the Warranty Documentation Portal or through IDS by selecting Coverage, Policy, Coding Questions and Mileage Corrections
Parts inquiries	Submit an IDS ticket to the Parts Department