

**SERVICE ACTION: ADD INSERT TO OWNER'S MANUAL**

Please perform the procedure outlined in this Service Information on all affected vehicles before customer delivery. In the event the customer has already taken delivery of the vehicle, please perform the procedure the next time the vehicle is in the shop.

MODEL

F39 (X2 Sports Activity Coupe)	F44 (2 Series Gran Coupe)	F90 (M5 Sedan)	F91 (M8 Convertible)
F92 (M8 Coupe)	F93 (M8 Gran Coupe)	F95 (X5 M Sports Activity Vehicle)	F96 (X6 M Sports Activity Coupe)
F97 (X3 M Sports Activity Vehicle)	F98 (X4 M Sports Activity Coupe)	G01 (X3 Sports Activity Vehicle)	G02 (X4 Sports Activity Coupe)
G05 (X5 Sports Activity Vehicle)	G06 (X6 Sports Activity Coupe)	G14 (8 Series Convertible)	G15 (8 Series Coupe)
G16 (8 Series Gran Coupe)	G22 (4 Series Coupe)	G23 (4 Series Convertible)	G26 (4 Series Gran Coupe)
G29 (Z4 Roadster)	G80 (M3 Sedan)	G82 (M4 Coupe)	G83 (M4 Convertible)

SITUATION

The printed owner's manual incorrectly specifies that fuel with up to 25% ethanol is allowed.



The label on the fuel filler flap correctly displays that fuel up to 10% ethanol content is allowed.

Fuel grade AKI 91 show; other models vary.

CAUSE

Incorrect information specified in the owner's manual.

CORRECTION

Add the supplementary sheet to the owner's manual.

Note: Vehicles will arrive from Vehicle Distribution Centers with the same sheet already in the glove compartment. Although such vehicles no longer show this Service Action as "open" and cannot be claimed for the repair, insert the sheet into the owner's manual during QC1.

PROCEDURE

Print the attachment (supplementary sheet) to this Service Information Bulletin, using conventional letter-size paper (8 ½ x 11").

Insert into vehicle owner's manual during QC1, prior to customer delivery.

PARTS INFORMATION

No parts are required

CLAIM INFORMATION

Reimbursement for this Action will be via normal claim entry utilizing the applicable work package information below that applies.

Defect Code:	0099310200	F39 F44 Gx U11 Insert supplementary sheet into Owner's Handbook
---------------------	-------------------	--

Completion before the first vehicle delivery to a customer or the vehicle is already in the workshop

Work Pkg	Labor Operation	Description (Plus work)	Labor Allowance
# 1	00 72 850	Print and insert the supplementary sheet into the Owner's Manual	3 FRU

Or:

The vehicle arrives at your center and this Action shows open (No other Main work will be performed or claimed during this workshop visit)

Work Pkg	Labor Operation	Description (Main work)	Labor Allowance
# 2	00 72 269	Print and insert the supplementary sheet into the Owner's Manual	5 FRU

Only one of the flat rate labor operation codes listed above can be used for claim submission and reimbursement. Also, only one Main work flat rate labor operation code can be claimed per workshop visit.

Claim Repair Comments

Only reference the SIB number and the work package (Pkg) number performed in the RO technician notes and the claim comments (For example: B00 09 22 WP 1), unless otherwise required by State law.

FEEDBACK REGARDING THIS BULLETIN

Technical Feedback	To submit feedback for the technical topics of this bulletin: Submit your feedback in the rating box at the top of this bulletin
Warranty Feedback	To submit feedback for the CLAIMS section of this bulletin: Submit an IDS ticket to the Warranty Department, or use the chat available in the Warranty Documentation Portal
Parts Feedback	To submit feedback for the PARTS section of this bulletin: Submit an IDS ticket to the Parts Department

Supporting Materials

[picture as pdf B00 09 22 Supplement.pdf](#)