



This Service Information bulletin replaces SI B04 18 15 dated July 2015

What's New:

- Purchasing information
- Accumulated Misfire Counter

INFORMATION

Distribution of the following On-Board Diagnostics (OBD) tool is complete. This tool is no longer available through the BMW Parts Department. Additional or replacement tools may be purchased online from various vendors. The recommended search parameters are Actron and CP9670.

The Actron CP9670 was initially distributed to diagnose the Malfunction Indicator Lamp ((MIL), aka "Service Engine Soon" lamp) illuminated with no relevant faults. For complete details on the MIL faults refer to SI B12 32 14.



New Functionality: Accumulated Misfire Counter.

WARRANTY INFORMATION

For Warranty service contact ACTRON at:

- www.actron.com
- Service and Support

Posted: Monday, December 17, 2018

