



RECALL 22V-614: EXHAUST GAS RECIRCULATION (EGR) COOLER

MODEL

E-Series	Model Description	Production Date	Affected Engine Type
G30	5 Series Sedan	October 9, 2017 – June 25, 2018	B57O

AFFECTED VEHICLES

Vehicles which require this Recall Campaign to be completed will show it as “Open” when checked either in AIR, the “Service Menu” of DCSnet (Dealer Communication System), ISPA Next or Warranty Vehicle Inquiry.

SITUATION

BMW AG is conducting a Voluntary Safety Recall (effective August 11, 2022) on certain Model Year 2018 BMW 540d xDrive vehicles with a 6-cylinder (“B57O”) diesel engine that were produced between October 9, 2017 and June 25, 2018.

Please note that similar recalls were conducted in 2021 and 2018. This new recall affects the remaining diesel engine model subject to the EGR Cooler recall.

Over time, the Exhaust Gas Recirculation (EGR) system’s cooler could internally leak cooling fluid. If the fluid combines with diesel engine soot particles, this could damage the engine intake manifold, and increase the risk of a fire.

The EGR cooler will need to be replaced. If a leak is detected in the intake manifold, it will also be replaced.

The Recall Notice and Q&A have been attached for further information.

The bulletin will be updated when additional information becomes available.

Supporting Materials

[picture as pdf B110222 Recall Notice.pdf](#)

[picture as pdf B110222_22V-614-G30d-EGR-Cooler-\(FAQ\)-\(10Aug2022\).pdf](#)