



Model

G05 (X5 Sports Activity Vehicle)	G07 (X7 SAV)	G20 (3 Series Sedan)	G29 (Z4 Roadster)
----------------------------------	--------------	----------------------	-------------------

Equipped with the B46, B58, or N63 produced thru June 20, 2019

Situation

The following faults are erroneously store in the Digital Motor Electronics (DME).

Fault code:	Control module:	Fault code text:
1A2014	DME	Electric fan, function: Switch-off due to undervoltage

There is no customer-facing symptom nor related check control message displayed.

Cause

A software error may cause this erroneous fault to be stored in the DME.

Correction

Erroneous fault **1A2014** can be ignored; it will be removed as of ISTA **4.17.1x** (estimate availability late June, 2019)

Procedure

If the following fault is stored: **1A2014**:

- Ignore the fault and clear fault memory **after all other** diagnostics have been completed.

Warranty Information

This service information bulletin provides technical, diagnostic and/or repair-related information.