

RECALL CAMPAIGN 19V-678: REPLACE BOTH SWIVEL BEARINGS

Please perform the procedure outlined in this Service Information on all affected vehicles before customer delivery. In the event the customer has already taken delivery of the vehicle, please perform the procedure the next time the vehicle is in the shop.

This Service Information Bulletin (Revision 1) replaces SI B31 05 19 dated October 3, 2019.

What's New:

· Parts Information

MODEL

| E-Series | Model Description | Production Date |
|----------|----------------------------|----------------------------------|
| G01 | X3 Sports Activity Vehicle | August 27 thru September 3, 2019 |
| G02 | X4 Sports Activity Coupe | August 25 thru August 26, 2019 |

AFFECTED VEHICLES

Vehicles which require this Recall Campaign to be completed will show it as "Open" when checked either in AIR, the "Service Menu" of DCSnet (Dealer Communication System), Key Reader or Warranty Vehicle Inquiry.

SITUATION

BMW of North America, LLC is conducting a Voluntary Safety Recall (effective September 19, 2019) on a small number of Model Year 2020 BMW vehicles that were produced between August 25, 2019 and September 3, 2019.

One or both swivel bearings of the front suspension may not have been produced to supplier specifications. They could become damaged, affect vehicle handling and control, and increase the risk of a crash.

<u>Potentially affected vehicles are not to be driven</u>. Handle the vehicles very carefully when moving into the workshop.

CAUSE

Both swivel bearings may not have been produced to supplier specifications.

CORRECTION

Replace both of the affected swivel bearings.

PROCEDURE

Handle the vehicles very carefully when moving into the workshop.

Replace both of the affected swivel bearing, as per repair manual RA 31 21 090 Replace left/right swivel bearing.

PARTS INFORMATION

Performing a part number look-up in ETK or AIR by VIN or model in place of using/invoicing the part numbers in this bulletin may result with the wrong parts being invoiced and installed.

Please refer to the Parts Matrix for the ordering procedure.

| Part Number: | Description: | Quantity: |
|-----------------|--|-----------|
| 31 20 6 872 920 | Spherical collar screw (M12x45) | 8 |
| 07 11 9 906 095 | Hexagon screw with flange (M12x1,5x80-10.9) | 2 |
| 37 10 6 789 678 | Hexagon nut with collar (M12x1,5-10 ZNS3) | 2 |
| 34 11 6 868 785 | Hex bolt (M6x12) | 8 |
| 34 21 1 161 806 | Inner hex bolt (M8x14) | 2 |
| 07 14 6 875 114 | Hexagon nut with collar (M16x1,5) | 4 |
| 34 50 9 804 151 | ASA screw, thread-forming (M6x16) | 2 |
| 31 20 6 866 022 | Collar bolt with compression spring (M16x1,5x66) | 2 |
| 34 10 6 864 424 | Torx screw with washer (M12X1,5X43 ZNS3) | 4 |
| 33 30 6 787 062 | Combination nut (M14x1,5) | 2 |
| 31 21 6 882 597 | Carrier, left (aka swivel bearing) | 1 |
| 31 21 6 882 598 | Carrier, right (aka swivel bearing) | 1 |
| | | |

Copyright ©2022 BMW of North America, Inc.

| Or, only for the M40i | | |
|-----------------------|-------------------------------------|---|
| 31 21 6 882 595 | Carrier, left (aka swivel bearing) | 1 |
| 31 21 6 882 596 | Carrier, right (aka swivel bearing) | 1 |

WARRANTY INFORMATION

Reimbursement for this Recall will be via normal claim entry utilizing the following information:

| Defect Code: | 0031960100 | Both swivel bearings |
|---------------------|------------|----------------------|

Completion before the first vehicle delivery to a customer or the vehicle is already in the workshop.

| Work Pkg | Labor Operation | Description (Plus work) | Labor Allowance |
|----------|------------------------|--|---|
| # 1 | 00 68 654 | Replacing both swivel bearings, includes checking wheel alignment (without load) and adjusting as necessary | 43 FRU (X3 sDrive RWD); 46 FRU (X3 xDrive and X4 xDrive AWD) |

Or:

The vehicle arrives at your center and this Recall Campaign shows open (No other Main work will be performed/claimed during this workshop visit)

| Work Pkg | Labor Operation | Description (Main work) | Labor Allowance |
|----------|------------------------|--|---|
| # 2 | 00 68 119 | Replacing both swivel bearings, includes checking wheel alignment (without load) and adjusting as necessary | 45 FRU (X3 sDrive RWD); 48 FRU (X3 xDrive and X4 xDrive AWD) |

Claim Repair Comments

Unless additional related/in conjunction work was required (not addressed and/or included in one of the options provided above), then only reference the SIB number and the work package (Pkg) number performed in the RO technician notes and in the claim comments (For example: B31 05 19 WP 1), unless otherwise required by State law.

And, as applicable:

Alternative Mobility Solution (AMS) for Vehicle Owners (RO and Claim Comments Required)

This Recall repair qualifies for Alternative Mobility Solution (AMS) expense reimbursement, claim this item under the Defect Code noted above as follows:

Sublet Code 2 - Itemize the AMS sublet amount on the repair order and in the claim comment section.

Please refer to SI B01 29 16 for additional information. Supporting Materials

<u>picture as pdf B310519 Attachment Q_A.pdf</u> <u>picture as pdf B310519 Recall Notice.pdf</u>