



MODEL

F22 (2 Series Coupe)	F23 (2 Series Convertible)	F25 (X3)	F26 (X4)
F30 (3 Series Sedan)	F31 (Series Sport Wagon)	F32 (4 Series Coupe)	F33 (4 Series Convertible)
F34 (3 Series Gran Turismo)	F36 (4 Series Gran Coupe)	G01 (X1)	G02 (X4)
G12 (7 Series Sedan)	G30 (5 Series Sedan)	G32 (6 Series Gran Turismo)	

SITUATION

The CCM assistance systems restricted or pedestrian protection system failed is displayed after deleting transport mode.

CAUSE

Electronic Power Steering (EPS) steering angle sensor was not taught in after deletion of transport mode.

INFORMATION

Check if EPS / steering angle sensor was taught-in after deletion of transport mode:

- This should have actually been done already after the deletion of transport mode;
- If this is not the case, the EPS / the steering angle sensor must be taught-in.

If the error continues, carry out another diagnosis with ISTA and if necessary work through the existing test modules.

WARRANTY INFORMATION

Not applicable.

Other Repairs

If the error continues and other eligible and covered work is performed as a result of performing the ISTA diagnostics and related test plans, claim this work with the applicable defect code and labor operations (including diagnosis) that are listed in the KSD2.