



MODEL

G05 (X5)

G07 (X7)

SITUATION

At temperatures below 32°F, jerking in the steering wheel may be felt.

CAUSE

Unfavorable software application for the steering

CORRECTION

ISTA 4.18.1x, I-level S18A-19-07-5xx

PROCEDURE

Program the vehicle with ISTA 4.18.1x to I level S18A-19-07-5xx or a more recent version.

ISTA 4.18.1x is expected to be available from 07/2019.

Note that ISTA will automatically reprogram and code all programmable control modules that do not have the latest software.

Always connect a BMW approved battery charger/power supply (SI [B04 23 10](#)).

For information on programming and coding with ISTA/P, refer to CenterNet/Aftersales Portal / Service / Workshop Technology / Vehicle Programming

A parts replacement does not provide a remedy and is not permitted

WARRANTY INFORMATION

Information only.