



MODEL

I12 (i8)			
Start of production to 05/30/2016			

SITUATION

Rattle/thumping noise in the area of the rear axle

Rear axle spring strut leaking oil

CAUSE

Rear axle spring strut

CORRECTION

Replace **both** spring struts of the rear axle

PROCEDURE

Refer to ISTA **REP37 12 10x** "Replacing rear left or right spring strut shock absorber"

PARTS INFORMATION

Part Number	Description	Quantity
37 10 6 884 588	Spring strut, EDC rear	2

WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks.

Defect Code:	33 52 00 15 00	
Labor Operation:	Labor Allowance:	Description:
37 12 151*	Refer to KSD	Replacing both rear spring strut shock absorbers

Labor operation code 37 12 151 is a Main labor operation. If you are using a Main labor code for another repair, use the Plus code labor operation 37 12 521 instead.