



## CREAKING NOISE FROM RIGHT TRUNK HINGE

**MODEL**

E-Series	Model Description	Production Date
F90	M5 Sedan	From March 3, 2020
G30	5 Series Sedan	From March 3, 2020

**SITUATION**

A creaking noise is present from the area of the right trunk hinge when opening or closing the trunk.

**CAUSE**

A faulty component inside the trunk spindle drive.

**CORRECTION**

Replace the trunk spindle drive.

**PROCEDURE**

Replace the spindle drive following repair instructions **REP 51 24 351** “**Removing/installing/replacing electrical spindle drive for trunk lid, right**”.

**PARTS INFORMATION**

Part Number	Description	Quantity
51 24 4A1FA90	Spindle drive, right	1

**CLAIM INFORMATION**

Covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks.

<b>Defect Code:</b>	<b>5124233900</b>	<b>Electric spindle drive (drive unit), rear lid (automatic rear lid actuation) Unpleasant noises</b>
---------------------	-------------------	---

Refer to AIR for the corresponding flat rate unit (FRU) allowances.

Labor Operation	Description	Labor Allowance
51 24 351	Removing/installing/replacing electrical spindle drive for trunk lid, right (Main work)	Refer to AIR
Or:		
51 24 851	Removing/installing/replacing electrical spindle drive for trunk lid, right (Plus work)	Refer to AIR

Based on which one applies to your center, please refer to **SI B01 01 20** or **B01 07 20** for claiming your diagnosis work time, job/repair work time (WT), RO/Claim WT and/or repair explanation procedures, unless otherwise required by State law.

**QUESTIONS REGARDING THIS BULLETIN**

Technical inquiries	Submit feedback at the top of this bulletin
Warranty inquiries	Please contact the Warranty department by either using the Live Chat that's available in the Warranty Documentation Portal or through IDS by selecting Coverage, Policy, Coding Questions and Mileage Corrections
Parts inquiries	Submit an IDS ticket to the Parts Department