



MODEL

G12 (7 Series)			
----------------	--	--	--

SITUATION

Rear roller sunblind will not deploy properly on one or both sides.

CAUSE

Connection points to slider or roller are broken.

CORRECTION

After identifying broken part, perform repair according to attached instructions.

PROCEDURE

For conditions that are similar to the situation described:

Follow Rear Roller Sunblind Damage Repair procedure attached.

PARTS INFORMATION

Part Number	Description	Quantity
51 46 7 936 971	Repair Kit, Roller sunblind	1

WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks.

Defect Code:	5146041300	
--------------	------------	--

Without Comfort Seats

Labor Operation:	Labor Allowance:	Description:
51 46 013	Refer to KSD2	Removing and Installing/Replacing the roller sunblind for the rear window (Main work).
Or:		
51 46 513	Refer to KSD2	Removing and Installing/Replacing the roller sunblind for the rear window (Plus work).

If you are using a Main labor code for another repair, use the Plus code labor operation 51 46 513 instead of 51 46 013.

Or:

With Comfort Seats

Labor Operation:	Labor Allowance:	Description:
51 46 015	Refer to KSD2	Removing and Installing/Replacing the roller sunblind for the rear window (with comfort seats in rear compartment) (Main work).
Or:		
51 46 515	Refer to KSD2	Removing and Installing/Replacing the roller sunblind for the rear window with (comfort seats in rear compartment) (Plus work).

If you are using a Main labor code for another repair, use the Plus code labor operation 51 46 515 instead of 51 46 015.

And, with the above that applies:

Labor Operation:	Labor Allowance:	Description:
51 99 000	6 FRU	Work time to repair the roller sunblind according to attached instructions.

Refer to KSD2 for the corresponding flat rate unit (FRU) allowances.

Work time labor operation code 51 99 000 is not considered a Main labor operation. Also, since the “work time” FRU allowance to be claimed is specified, a separate punch time is not required.

ATTACHMENTS

View PDF attachment [B512717 Attachment A -Rear Roller Sunblind Damage Repair](#).