



This Service Information bulletin supersedes S.I. B64 21 92 **dated April 2003 and S.I. B64 01 90 (3042) dated March 1993.**

MODEL

All

INFORMATION

The following is a listing of information for servicing BMW Air Conditioning systems. Please refer to the TIS Website/Operating Fluids Information/Group 64 for proper air conditioning refrigerant/oil capacities when evacuating/recharging BMW A/C systems.

Note that some 1993 Model Year early production R-134a equipped vehicles have under-hood labels that specify higher charge values than those specified in the Operating Fluids Information. Testing has confirmed that the values given in the Operating Fluids Information are the optimum fill capacities. Please consult the Operating Fluids Information for the proper charge amount. However, inadvertent refrigerant charging up to the fill capacity given on the original under-hood label will not cause any problems.