

**SERVICE ACTION: REPLACE THE PEDESTRIAN PROTECTION SENSOR**

Please perform the procedure outlined in this Service Information on all affected vehicles before customer delivery. In the event the customer has already taken delivery of the vehicle, please perform the procedure the next time the vehicle is in the shop.

MODEL

G01 (X3)

AFFECTED VEHICLES

This Service Action involves some X3 vehicles produced between 11/18/2016 and 2/7/2017.

Vehicles which require this Service Action to be completed will show it as "Open" when checked either in AIR, the "Service Menu" of DCSnet (Dealer Communication System) or with the Key Reader.

SITUATION

The active hood for pedestrian protection may not be activated in a collision.

CAUSE

Manufacturing error in the pedestrian protection sensor.

CORRECTION

Replace the pedestrian protection sensor.

PROCEDURE

Replace the pedestrian protection sensor, see REP 65 76 630

PARTS INFORMATION

Part Number	Description	Quantity
65 76 6 833 256	Pedestrian protection sensor	1

WARRANTY INFORMATION

Reimbursement for this Service Action will be via normal claim entry utilizing the following information:

Defect Code:	65040300	
Labor Operation:	Labor Allowance:	Description:
00 65 869	14 FRU	Replace the pedestrian protection sensor (Plus work)

ATTACHMENTS

View PDF attachment [REP 65 76 630](#).

View PDF attachment [Location of Pedestrian Protection Sensor](#).

