

**DISPLAY KEY NOT DETECTED BY VEHICLE**

This Service Information Bulletin (Revision 1) replaces TRI 66 06 18 dated February 2018.

This bulletin is information only, no claim information intended.

What's New (Specific text highlighted):

- This Service Bulletin B66 06 18 replaces TRI 66 06 18. There is no content change.

MODEL

E-Series	Model Description	Affected Option Code
G01	X3 Sports Activity Vehicle	Equipped with SA3DS BMW display key
G02	X4 Sports Activity Coupe	
G12	7 Series Sedan	
G30	5 Series Sedan	
G32	640i xDrive Gran Turismo	

SITUATION

Display key is not detected by the vehicle. Movement of the display key to various locations in reference to the vehicle has no effect.

The error only occurs while vehicle is in transport mode (or directly after deactivation of transport mode).

This error does not occur after customer delivery.

INFORMATION

The display key is not designed to be detected while the vehicle is in transport mode.

As soon as transport mode is deactivated, the display key should be detected properly. If it is not, simply actuating the locking or unlocking button. It will then operate and be detected and continue to operate and be detected.

If the vehicle is put back into transport mode, the display key will no longer be detected.