



This Service Information bulletin supersedes SI B71 01 15 dated January 2015.

MODEL

I01 (i3 and i3 REx)	I12 (i8)
---------------------	----------

SITUATION

The model year is incorrect on the emissions compliance label on certain I01 and I12 vehicles produced from November 1, 2014 through December 22, 2014.

In order to remedy the situation, BMW is conducting a Voluntary Emissions Recall Campaign to replace the emissions compliance label on all affected vehicles.

AFFECTED VEHICLES

This Emissions Recall Campaign involves certain I01 (i3 and i3 REx) and I12 (i8) vehicles in which the emissions compliance label must be replaced.

In order to determine whether a specific vehicle has had this Emissions Recall Campaign completed or is affected by this Emissions Recall Campaign, first check whether the Emissions Recall Completion Label, SD 92-435, is attached to the right (passenger) rear side of the hood in the engine compartment, close to the windshield. If the label is found, the Campaign has already been performed. If the Emissions Recall Completion Label is not present, it will be necessary to utilize the "Service Menu" of DCSnet (Dealer Communication System) or the Key Reader. Based on the response of the system, either proceed with the corrective action or take no further action.

PROCEDURE

Only properly trained personnel, who have passed all applicable technical training courses, should perform any maintenance or repairs on any Hybrid or Electric Vehicle. Work performed by unqualified persons may result in severe injury or damage to the vehicle. Additional information may be found in REP 61 00... Observe safety instructions when handling electric vehicles.



1. Locate and remove the emissions label with a hot air gun. The illustration indicates the locations of the emissions label.

Note: The incorrect emissions label displays 2015 MY.

2. Clean the glue residue from the surface area with an appropriate cleaner.





3. Install the correct emissions label that displays 2014 MY.

PARTS INFORMATION

Part number	Description	Quantity
71 22 8 628 988	Emissions label I01 BEV	1
71 22 8 642 359	Emissions label I01 REx	1
71 22 8 635 922	Emissions label I12	1

LABEL INSTRUCTIONS

	<p>After the vehicle has been checked and corrected, obtain a label (SD 92-435) and with the indelible marker provided, legibly print the Recall name, Recall number, and dealer code (5 digits) on the "Emissions Recall Campaign Completed Label" (see illustration).</p> <p>Note: Additional labels can be ordered online at BMW TIS.</p>
--	---



For California centers only: It is required by the California Code of Regulations that an executed orange "Vehicle Emission Recall - Proof of Correction" certificate (SD92-084, see illustration) be provided to each customer (for vehicles registered in the state of California), once the Recall on his or her vehicle has been completed.

WARRANTY INFORMATION

Reimbursement for this Recall will be via normal claim entry utilizing the following information:

Defect Code:	00 71 17 02 00
---------------------	-----------------------

Completion before vehicle delivery to the customer or the vehicle is already in the workshop

Labor Operation:	Labor Allowance:	Description:
00 62 933	Refer to KSD2	Replace emissions label (Plus work)

Completion after vehicle delivery to the customer

Labor Operation:	Labor Allowance:	Description:
00 62 270	Refer to KSD2	Replace emissions label (Main work)

Labor operation code 00 62 270 is a Main labor operation.

ADDITIONAL INFORMATION

Perform the procedure outlined in this service information on all affected vehicles BEFORE customer delivery or the next time they are in the shop for maintenance or repairs.

BMW centers must ensure Recalls are completed after having been notified by BMW of North America, LLC (BMWNA) that a safety-related defect or noncompliance exists in any motor vehicle or item of replacement equipment in the center's possession at the time of notification. In BMW NA's case, this notification would typically be made by the issuance of a Recall notification in the form of a Service Information bulletin (SIB) or transmission of a Dealer Communication System (DCS) Recall message.

Under the National Traffic and Motor Vehicle Safety Act of 1966, as amended, if a Recall campaign is announced by BMW NA, centers must ensure that all Recalls on new vehicles and new items of replacement equipment are completed BEFORE delivery to the consumer. This means that centers may not legally deliver new motor vehicles or new items of replacement equipment to consumers with an open Recall.

The Safety Act also prohibits centers from selling or leasing the motor vehicle or item of replacement equipment, unless and until the open Recall has been completed BEFORE delivery. This also pertains to vehicles in the Certified Pre-Owned program, and to items of replacement equipment.

Finally, BMW centers should not sell or use parts that have been recalled by BMW NA. Please follow the specific instructions provided by BMW NA on the return or disposition of the parts.