



RECALL CAMPAIGN 16V-914: AUTOLIV AIR BAG

Please perform the procedure outlined in this Service Information on all affected vehicles before customer delivery. In the event the customer has already taken delivery of the vehicle, please perform the procedure the next time the vehicle is in the shop.

This Service Information bulletin replaces SI B72 02 16 **dated February 2017**

MODEL

I01 (i3)	I01 (i3 REx)	I12 (i8)
----------	--------------	----------

**SITUATION**

All vehicles affected by this Recall have been repaired.