



This Service Information bulletin supersedes SI B00 02 13 **dated March 2013.**

MODEL

E84

SITUATION

Model	Production Start*	Comments
X1 sDrive28i, xDrive28i, xDrive35i	3/13	 New Condition Based Service (CBS) interval as of 7/13 vehicle production.

* availability approx. 1 month later

17-digit Vehicle Identification Number (VIN): The 10th digit (model year identifier) utilizes the letter “E” for MY 2014.

Quality Certification 1 (QC1):

A new QC1 form has been developed for the 2014 models covered in this bulletin: SD92-450. Refer to Attachment 1.

Delivery check, technician: Change the navigation route criteria (if equipped) from “ECO PRO” to “Fast Route” using iDrive.

For more information on the X1's maintenance requirements, refer to [B00 04 12](#).

Maintenance

2014 model year X1 built prior to July 2013 utilized a 15,000 mile/24 month engine oil Condition Based Service (CBS) interval. The interval is triggered by the presence of option code 8KC.

All 2014 model year X1 produced starting in July will incorporate a new basic interval for the engine oil service. The new CBS interval is every 10,000 miles or 12 months (option code 8KL).

The Key Reader/ISPA Light application will recognize the production month and/or the respective option code, and specify the corresponding interval and its related maintenance operations.

BMW vehicles' CBS computes the actual optimum maintenance requirements based not only upon the accumulated mileage, but also taking into account important factors pertaining to fuel consumption such as high or low engine speeds, short or long-trip driving. Such computations can result in variations from the 10,000 mile interval and correspondingly, when an engine oil service will actually display “Recommended” or “Due.” The mileage intervals listed below are for reference only.

CBS counter #	Approx. cumulative miles	Operation (with option code 8KL)
1	10,000	Replace the engine oil and filter.
2	20,000	Replace the engine oil and filter.
		Replace the ventilation microfilter (connected service).
3	30,000	Replace the engine oil and filter.
		Vehicle check (or at 48 months; non-connected service)

4	40,000	Replace the engine oil and filter.
5	50,000	Replace the engine oil and filter.
		Replace the engine air filter (connected service).
6	60,000	Replace the engine oil and filter.
		Replace the spark plugs (connected service).

The brake fluid replacement interval has also been changed. The first fluid change is now scheduled for 3 years after the vehicle's production date. Each subsequent brake fluid change is at 2-year intervals.

General Notes

2014 Service and Warranty Information booklets:

X1, all versions	SD92-445
------------------	----------

PARTS INFORMATION

Under separate cover, one pack of the Quality Certification I form for the 2014 BMWs covered in this bulletin will be sent to each BMW center's Service Manager. Additional copies may be ordered as listed below:

Item	Description	Qty	Price
SD92-450	Quality Certification I form (2014 X1)	1 pack	\$2.50
		(= 10 forms)	

These items are available online at BMW TIS under Materials Ordering. Refer to [B10 02 02](#) for instructions on how to place an order.

WARRANTY INFORMATION

Reimbursement of the BMW Pre-Delivery Inspection (Quality Certification 1) on 2014 BMWs is via submission of a warranty claim when the work is completed.

- If the Display and Delivery portions of the inspection are performed separately, individual claims should be submitted when those operations are performed.
- If the entire QC1 delivery inspection is performed at the same time, submit one claim for "Spot Delivery." This is an important difference from the prior process, and claims must not reflect Display and Delivery if only the Spot Delivery was actually performed.
- All BMWs are only eligible for either the Display and Delivery Inspection, or the Spot Delivery Inspection.
- If a BMW center performs the Display Inspection and the vehicle is traded, then the second center may only perform and claim the Delivery Inspection. Check the DCS Vehicle History Report to determine whether a claim for this work had been submitted by another center.
- If a center receives a vehicle, does nothing to it and then trades it to another center, then the second center may perform the Display and Delivery Inspection or the Spot Delivery Inspection, whichever is relevant. Check the DCS Vehicle History Report to determine if a claim for this work had been submitted by another center.

BMW Company Vehicles

Reimbursement for performing the QCI on BMW company vehicles of any model year for regional employees of BMW of North America must still be requested by submitting a claim through DCS. Use the Spot Delivery codes listed below:

--	--

Defect Code:	11 99 99 77 BV
Labor Operation:	00 00 012
Flat Rate Units:	Refer to KSD2

Refer to KSD2 for the corresponding flat rate unit (FRU) allowance. Enter the Chassis Number, which consists of the last 7 digits of the Vehicle Identification Number (VIN). Click on the “Search” button, and then enter the applicable flat rate labor operation in the FR code field.

Note: BMW company vehicles delivered to field personnel may have already received a full QCI at the VDC (vehicle distribution center) which serves your region. This should be evident upon arrival at your center by the following:

- The absence of the usual protective seat and door panel covers
- Transport mode has been deactivated (radio is operational)
- The Monroney label not being affixed to the window, etc.
- VDCs affix a small orange-colored label onto the center console near the transmission selector lever which reads “QC1 already done at VDC!” If this label is found, remove it prior to delivery to the employee.

Please verify that the QC1 has already been performed at a VDC on a specific vehicle by contacting your regional Distribution Manager with the chassis number.

IMPORTANT:

As with all work that is reimbursed by BMW, the repair order, time recording, and record keeping requirements outlined in the Warranty Policy and Procedures Manual must be strictly observed. Quality Certification I payments are subject to audit.

Attachments

1 QC1 checklist SD92-450

ATTACHMENTS

View PDF attachment [B000213 Attachment 1](#).