



MODEL

G01 (X3 SAV)

ZDB

5AT

SITUATION

BMW Group is conducting a Voluntary Safety Recall on Model Year 2018 - 2019 BMW X3 SAV vehicles. This delivery stop/recall involves vehicles with the option "Active Lane Keeping Assistant". Potentially affected vehicles may have been equipped with an incorrect steering wheel. The steering wheel will be inspected and, if necessary, replaced.

AFFECTED VEHICLES

This Recall Campaign involves 53 BMW X3 SAV vehicles produced from April 26, 2018 – May 2, 2018.

Vehicles which require this Recall Campaign to be completed will show it as "Open" when checked either in AIR, the "Service Menu" of DCSnet (Dealer Communication System) or with the Key Reader. The affected vehicles will be identified with the description:

Affected customer will be notified via First Class Mail in August 2018.

CAUSE

The incorrect steering wheel was installed into the vehicle during assembly.

CORRECTION

The steering wheel will be inspected and, if necessary, replaced.

PROCEDURE

Remove the airbag from steering wheel as described in repair manual 32 34 030



A bar code label for the steering wheel can be found in the circled area as shown on left.

Check the serial number on the bar code label as shown and compare it to the list below.



If the serial number matches the list to the left, then the steering wheel should be replaced as described in repair manual 32 33 015.

ITEM (FG SERIAL NUMBER)
SW94959130118B01204K0188128461
SW94959130118B01214K0053128461
SW94959130118B01214K0554128461
SW94959130118B01204K0816128461
SW94959130118B01204K0871128461
SW94959130118B01214K0031128461
SW94959130118B01204K0159128461
SW94959130118B01204K0195128461
SW94959130118B01214K0559128461
SW94959130118B01204K0196128461
SW94959130118B01214K0038128461
SW94959130118B01214K0558128461
SW94959130118B01204K0815128461
SW94959130118B01204K0868128461
SW94959130118B01214K0050128461
SW94959130118B01204K0867128461
SW94959130118B01204K0870128461
SW94959130118B01214K0034128461

PARTS INFORMATION

Part Number	Description	Quantity
32 30 6 883 777	Sports Steering Wheel	1 as needed

WARRANTY INFORMATION

Reimbursement for this Recall repair campaign will be via normal claim entry utilizing the Defect Code provided below:

Defect Code:	0032730200	
---------------------	-------------------	--

Completion “before” vehicle delivery to the customer or the vehicle is already in the workshop

Labor Operation:	Labor Allowance:	Description:
00 66 707	3 FRU	Remove the steering wheel airbag module and inspect the label, no repair is necessary (Plus work)
Or:		
00 66 708	5 FRU	Remove the steering wheel airbag module, inspect the label, and replace the steering wheel (Plus work)

Or:

Completion after vehicle delivery to the customer

Labor Operation:	Labor Allowance:	Description:
00 66 124	5 FRU	Remove the steering wheel airbag module and inspect the label, no repair is necessary (Main work)
Or:		
00 66 125	7 FRU	Remove the steering wheel airbag module, inspect the label, and replace the steering wheel (Main work)

TREAD Act - Previous Customer-Pay Repairs

Based on the small number affected vehicles and their current age, reimbursement requests for prior customer-pay repairs that specifically address the issue described in this Recall bulletin are not very likely.

[B320618 Recall Notice.pdf](#)

[2018-G01-SteeringWheel-QA-\(30May2018\).pdf](#)

[REP 32 33 015.pdf](#)

[REP 32 34 030.pdf](#)