

LR SEAT BACK UNLOCKED CCM / SEAT NOT LATCHING

E-Series	Model Description	Production Date	Affected Option Code
F95	X5 M Sports Activity Vehicle		Vehicles equipped with standard equipment
F96	X6 M Sports Activity Vehicle		
G05	X5 Sports Activity Vehicle		
G06	X6 Sports Activity Vehicle		•
G07	X7 Sports Activity Vehicle		benon seat.

SITUATION

Refer to attachment for full details. Supporting Materials picture as pdf B52 04 22_REV00.pdf