



RETRACTABLE HARDTOP STATUS REQUEST SUPPLEMENT

This Service Information Bulletin (Revision 5) replaces SI B54 09 07 **dated June 2019**.

What's New (Specific text highlighted):

- Model
- Attachments

MODEL

E93 (3 Series Convertible)	F33 (4 Series Convertible)	F83 (M4 Convertible)	G14 (8 Series Convertible)
I15 (i8 Roadster)	G23 (4 Series Convertible)		

INFORMATION

- Documents have been developed (see attachments) showing the known correct statuses for all hall sensors and microswitches used to operate the retractable hard top (RHT).
- This document is intended to act as a supplement to the diagnostic information available in ISTA.
- Comparing these statuses to the actual statuses of a vehicle with a functional problem may assist in narrowing down which sensor/switch is contributing to the functional problem.

QUESTIONS REGARDING THIS BULLETIN

Technical inquiries	Submit feedback at the top of this bulletin
Warranty inquiries	Submit an IDS ticket to the Warranty Department or use the chat available in the Warranty Documentation Portal
Parts inquiries	Submit an IDS ticket to the Parts Department

Supporting Materials

[picture as pdf B54 09 07 attachment 2 F33 F83 .pdf](#)

[picture as pdf B54 09 07 attachment 3 I15.pdf](#)

[picture as pdf B54 09 07 attachment 5 G23.pdf](#)

[picture as pdf B54 09 07 attachment 4 G14.pdf](#)

[picture as pdf B54 09 07 attachment 1 E93.pdf](#)