



VEHICLE AT STANDSTILL WIPER SPEED RESET FUNCTION DISABLED

This Service Information Bulletin (Revision 2) replaces TRI 61 32 17 **dated April 2019**.

This bulletin is information only, no claim information intended.

What's New (Specific text highlighted):

- This Service Bulletin B61 32 17 replaces TRI 61 32 17. There is no content change.

MODEL

E89 (Z4 Roadster)	F06 (6 Series Gran Coupe)	F07 (5 Series Gran Turismo)	F10 (5 Series Sedan)
F12 (6 Series Convertible)	F13 (6 Series Coupe)	F15 (X5)	F16 (X6)
F22 (2 Series Coupe)	F23 (2 Series Convertible)	F25 (X3)	F26 (X4)
F30 (3 Series Sedan)	F31 (3 Series Sport Wagon)	F32 (4 Series Coupe)	F33 (4 Series Convertible)
F34 (3 Series Gran Turismo)	F36 (4 Series Gran Coupe)	F48 (X1 sDrive 28i or xDrive 28i)	F80 (M3 Sedan)
F82 (M4 Coupe)	F83 (M4 Convertible)	F85 (X5 M)	F86 (X6 M)
F87 (M2 Coupe)	G12 (7 Series)	G30 (5 Series)	G32 (6 Series Gran Turismo)
I01 (i3 & i3 REx)	I12 (i8)		

F15, F16, F25, F26, F85, F86 - production since 04/2017

Except F15, F16, F25, F26, F85, F86 - production since 03/2017

INFORMATION

Since 03/2017 (with noted exceptions), the automatic wiper speed reset function which lowers the wiping speed of the windshield wipers has changed. Now when the vehicle comes to a standstill while driving the wipers will continue to wipe at the same speed.

If the customer presses the button at the end of the wiper lever to activate rain sensor mode, the wipers will continue to function as before and wipe based on the amount of rain on the windshield.

Vehicles with SA822 option will no longer have this feature after 07/2017.