



RECALL 19V-XXX: HEADLAMP CONTROL UNIT

This Service Information Bulletin (Version 1) replaces SI B11 14 19 dated **November 21, 2019**.

What's New:

- This Delivery Stop has been upgraded to a Recall.

MODEL

Engineering Designation	Model Description	Production Date
G20	3 Series Sedan	July 22, 2019 – October 18, 2019
G29	Z4 Roadster	July 16, 2019 – August 20, 2019

AFFECTED VEHICLES

Vehicles which require this Campaign to be completed will show it as "Open" when checked either in AIR, the "Service Menu" of DCSnet (Dealer Communication System), ISPA Next or Warranty Vehicle Inquiry. All other systems will show the stop sale starting tomorrow.

SITUATION

BMW of North America, LLC has issued a Delivery Stop (effective November 21, 2019) on a small number of Model Year 2020 BMW vehicles that were produced between July 16, 2019 and October 18, 2019. During supplier production, the headlamp control unit may not have been produced to specifications.

Approximately 68 vehicles are affected by this Delivery Stop/Recall.

This Delivery Stop has been upgraded to a Recall (effective November 27, 2019).

The bulletin will be updated when additional information becomes available.

Supporting Materials

[picture as pdf 2019-G20-29-J29-HeadlampControlUnit-QA-\(27Nov2019\).pdf](#)

[picture as pdf B630819 Recall Notice.pdf](#)