

**AC TEMPERATURE FLUCTUATION OR LOSS OF COOLING N63 S63 N74**

This Service Information Bulletin (Revision 1) replaces B64 08 21 dated September 2021

Whats New:

- Procedure: Tool number correction

MODEL

F90 (M5 Sedan)	F91 (M8 Convertible)	F92 (M8 Coupe)	F93 (M8 Coupe)
F95 (X5 M)	F96 (X6 M)	G05 (X5 SAV)	G05 (X6 SAC)
G07 (X7 SAV)	G12 (7 Series Sedan)	G14 (8 Series Coupe)	G15 (8 Series Convertible)
G16 (8 Series Gran Coupe)	G30 (5 Series Sedan)	G32 (6 Series Gran Turismo)	

Vehicles equipped with N63, S63 V8 engines or N74 V12 engine.

SITUATION

Please refer to the attached pdf (B64 08 21)

Supporting Materials

[picture as pdf B640821_REV01.pdf](#)