



## AC TEMPERATURE FLUCTUATION OR LOSS OF COOLING PHEV

This Service Information Bulletin (Revision 4) replaces SI B64 09 21 **dated June 2022**.

**What's New** (Specific text highlighted):

- Procedure, Parts sections: For the **G05** PHEV there is a repair kit available that includes the EKK, Air conditioning condenser with dryer flask, Compressor to condenser pressure line, expansion valve shutoff valve and an electrical expansion valve.

**MODEL**

<b>E-Series</b>	<b>Model Description</b>	<b>Production Date</b>	<b>Engine</b>
G05	X5 xDrive45e PHEV Sports Activity Vehicle	From Start of Production (SOP) to October 1, 2021	With XB1 engine
G20	3 Series 330e PHEV Sedan	From SOP to January 31, 2022	With XB1G engine

**SITUATION**

Please refer to the attached pdf (B64 09 21)

Supporting Materials

[picture\\_as\\_pdf B64 09 21\\_REV04.pdf](#)