



RECALL 22V-240: AIR BAG CONTROL UNIT

This Service Information Bulletin (Revision 1) replaces SI B65 03 22 **dated April 2022**.

What's New (Specific text highlighted):

- NHTSA Recall Number 22V-240 assigned
- Warranty Claim Information updated
- Situation

Please perform the procedure outlined in this Service Information on all affected vehicles before customer delivery. In the event the customer has already taken delivery of the vehicle, please perform the procedure the next time the vehicle is in the shop.

MODEL

E-Series	Model Description	Production Date
I20	iX Sports Activity Vehicle	October 14, 2021 – April 7, 2022

AFFECTED VEHICLES

Vehicles which require this Recall Campaign to be completed will show it as "Open" when checked either in AIR, the "Service Menu" of DCSnet (Dealer Communication System), ISPA Next or Warranty Vehicle Inquiry.

SITUATION

Remedy for this recall is no longer valid and the remedy status has changed to "Remedy Not Available". New repair will be under B65 06 22 once the new remedy is available.

July 8, 2022

Supporting Materials

[picture as pdf B650322 Recall Notice.pdf](#)

[picture as pdf B650322_22V-240-FAQ-\(19Apr2022\).pdf](#)