



MODEL

G05 (X5 xDrive40i Sports Activity Vehicle)	G07 (X7 xDrive40i SAV)	G12 (740i, 740i xDrive Sedan)
--	------------------------	-------------------------------


SITUATION

Distribution of the following tool will be through the Automatic Tool Shipment Program. Additional tools may be purchased through your Regional Distribution Center (RDC). All prices in this bulletin are introductory prices and are only valid during the Automatic Tool Shipment.

Shipments of special tools may be delayed up to 2 weeks (after publication) depending on the RDC workload.



Turbocharger Attachment Chains
Order P/N 83 30 2 466 467
Price= \$116.00



- The turbocharger attachment chains are used with securing device P/N 83 30 2 446 919 (refer to **B04 04 17**)
- This illustration shows the proper initial attachment of the chains to 83 30 2 446 919 (1)



1. Wrap the chain around the turbo and attach to the securing device (3).
2. Final torque on the attachment chains (1) is 5 Nm.
3. Refer to ISTA Z4 (G29) operation 11 65 020 for complete instructions.



Note: The G29's turbo does not utilize this special tool, but its ISTA operation clearly depicts the usage on the affected vehicles.

WARRANTY INFORMATION

Terms of the Parts Department Special Tool Warranty can be viewed and printed by following the path below:

- Go to TIS 2.0
- Select “Tools and Equipment”
- Select “FAQ & Top Links”
- Select “Special Tool Warranty Information”