SIB 12 12 17 Catalyst Efficiency Fault 180001 Stored in DME With No MIL

MODEL

F22 (2 Series Coupe)	F23 (2 Series Convertible)	F30 (3 Series Sedan)	F31 (3 Series Sport Wagon)
F32 (4 Series	F33 (4 Series	F34 (3 Series Gran	F36 (4 Series Gran
Coupe)	Convertible)	Turismo)	Coupe)
G12 (7 Series)	G30 (5 Series Sedan)		

With B46O, B48M, B48O, B58M or XB1H engines

Except G12, G30 – production up to July 2017

G12, G30 – production up to March 2017

SITUATION

This bulletin has been removed because the diagnosis and recommended repair procedure has been implemented into ISTA.