



RECALL 20V-601: HIGH-VOLTAGE BATTERY

This Service Information Bulletin (Revision 5) replaces SI B61 21 20 **dated December 2020**.

What's New:

- Q&A has been updated

Please perform the procedure outlined in this Service Information on all affected vehicles before customer delivery. In the event the customer has already taken delivery of the vehicle, please perform the procedure the next time the vehicle is in the shop.

MODEL

E-Series	Model Description	Production Date
I12	i8 Coupe	March 2, 2020 – March 18, 2020
I15	i8 Roadster	May 20, 2020

AFFECTED VEHICLES

Vehicles which require this Campaign to be completed will show it as "Open" when checked either in AIR, the "Service Menu" of DCSnet (Dealer Communication System), ISPA Next or Warranty Vehicle Inquiry.

SITUATION

There are no more open VINS... Campaign is closed per Tara Leegwater.. (2/24/2022)

Supporting Materials

[picture as pdf B612120_20V-601-FAQ-\(23Dec2020\).pdf](#)

[picture as pdf B612120 Recall Notice_BMWi.pdf](#)